RES. CONTROL TGOING LTR NO.

3870. Z 3RF 0247 EGEG ROCKY FLATS

| DIST. LTR ENG | EG&G ROCKY FLATS, INC. -ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000 | |
|----------------------------|---|--|
| MAN, H.S. NCH, D.B. | | |
| NIVAL, G.J. | • | |
| iš, J.a. | - - February 4, 1993 | 93-RF-0267 |
| REPA, D.W. | _ rootaay 4; root | 00 111 020 |
| MAN. L. K. | <u>.</u> | |
| | Frazer R. Lockhart | |
| SH. J.M. JY. W.A. | Environmental Restoration Division | |
| STER. A.W. | DOE, RFO | • |
| IN, H.P. XX, G.E. | - USE OF WASTE PROCESS SYSTEM AND SOLAR POND WASTE TRANSFER LINI | =_ |
| ONALD M.M. | - EML-139-93 | - - |
| YTROSE J.K. | • | |
| TER, G.L. | The Solar Evaporation Ponds at Rocky Flats currently receives water collect | |
| VIO V.M. X | Interceptor Trench System (ITS). In April 1992, DOE, the Colorado Depar | |
| PLER. R.L. | (CDH), and the Environmental Protection Agency (EPA) agreed to an Interi- Measure/Interim Remedial Action (IM/IRA) to divert the trench water to the | |
| WART, D.L. UVAN, M.T. | constructed modular surge tanks and, subsequently, to evaporators for trea | |
| INSON E.R. KINSON, R.B. | remedy was chosen to allow required closure activities for the ponds to proc | |
| SON J.M. 'E, J. O. | accordance with the Rocky Flats Interagency Agreement (IAG), the Colorado | |
| HER XX | Waste Act (CHWA), the Comprehensive Environmental Response, Compensal Liability Act (CERCLA), the Resource Conservation and Recovery Act (RCR/ | |
| WW. R K | - National Oil and Hazardous Substances Pollution Contingency Plan (NCP). | • • |
| PENE MY | behind the schedule proposed in the IM/IRA Decision Document, and EG&G F | locky Flats is |
| ADAGNOU, X | working to achieve the diversion by April 16, 1993. | |
| CKSON D X | . In order to expedite the diversion of ITS water and to begin removing excess. | pond water as |
| WOONLY X | soon as possible, it will be necessary to use an existing waste transfer line | |
| WEER A X | from the Solar Evaporation Ponds to Building 374. This line runs through | |
| PHER, N. U | 771, 776, and 778. At several points the line penetrates building walls we secondary containment, which is non-compliant with secondary containment. | |
| RES CONTROL X X | requirements. Additionally, several non-welded (bolted) valves exist along | |
| WALK 53.7 X | are not secondarily contained. Similar situations exist for other lines at Ro | |
| ASSIFICATION: Y | other requirements, such as fire codes, also affect wall penetrations. We ha | ve contacted |
| SNI I | CDH, and they have indicated verbally that until the Issue is resolved plant | |
| ICLASSIFIED X X | lines can be used in their current configuration if compensatory measures place. | are put in |
| CRET | _ pace. | |
| HORIZED CLASSISIER | EG&G Rocky Flats proposes to divert the trench water to the new modular ta | nks and use the |
| SIGNATURE (UVV) | waste transfer line to ship interceptor trench water from the Solar Ponds ta | |
| -/3-93 | water from the B ponds to Building 374 for treatment. Use of the transfer necessary to obtain compliance, per the IM/IRA. Additionally, expediting the | |
| TĘ | diversion from the ponds will expedite the schedule for removing excess was | |
| REPLY TO RFP OC NO: | ponds. This will diminish the hydraulic driver for the contaminated sludge | |
| TION ITEM STATUS | currently has a potential to spread into the soil beneath cracked pond liners | |
| OPEN CLOSED | V | |
| TA PARTIAL R APRROVALS: | C | OCUMENT CLASSIFICA |
| em L | | REVIEW WAIVER PEI CLASSIFICATION OFFI |
| RIG & TYPIST INITIALS | | |

OCUMENT CLASSIFICATION REVIEW WAIVER PER CLASSIFICATION OFFICE

Frazer R. Lockhart February 4, 1993 93-RF-0267 Page 2

Due to the lack of secondary containment in some sections of the transfer line, EG&G Rocky Flats will visually inspect such sections and, at each wall penetrated by the line, inspect around the penetration for signs of leakage as a compensatory measure. The inspection will be performed once per shift when the transfer line is in use. Additionally, work is underway to provide secondary containment to the bolted valves.

If the use and compensatory measure explained above is unacceptable, or if you have other direction regarding this measure, please contact me by February 5, 1993. For further discussion, please contact E. M. Lee, Solar Ponds Program Manager on 966-8648.

E. M. Lee

Program Manager

Solar Ponds Remediation Program

EG&G Rocky Flats, Inc.

KCL:apt

Orig. & 1 cc - F. R. Lockhart

 ∞ :

J. K. Hartman - DOE, RFO